

PRESSURE DIAGRAMM

ISO 9001


WTO

Maximum possible coolant pressure depends on RPM.
Every sealing system has an individual diagram.
Select the suitable diagram by the number stated in the
data sheet of the driven precision tool.


ATTENTION:

Do not run dry! Coolant must be switched on before rotating.
For machining cast iron, only use driven tools with diagram D01012 or D01013.
1 bar = 14.5 PSI Filtration of minimum 50 µm recommended


D01001




D01002




D01003




D01007




D01010



D01011



D01012



D01013

